

# PRO INLINE SCREEN

## WHAT IT DOES:


The Pro Inline Screen captures the particles and vegetation in the water you are pumping to your machine and prevents them from plugging the holes in the spray bars of your equipment.



## SET UP:

Connect a discharge hose from the pump to the inlet end of the Inline Screen. The arrows on the body indicate the water flow direction. Connect the second discharge hose to the outlet end of the Inline Screen, using additional hose as required to connect to the equipment you are running.

The diagram below shows a typical connection sequence using a 2" pump and 1 1/2" discharge hose to the desired prospecting equipment.



## CLEAN UP:

Shut down the pump. Disconnect the Pro Inline Screen from the hoses. Unscrew the Pro Inline Screen at the threaded coupling. Rinse the screen and the tube sections in the clean water source you are pumping from. Screw the Pro Inline Screen back together at the threaded coupling. Reconnect your hoses, start the pump and, and resume processing your material.

SUMMIT MINING & EQUIPMENT INC.

sales@summitmining.com . www.summitmining.com

503-746-5532 . 6670 SW 169th Ave. Beaverton, OR 97007

OUR MISSION: To make the gold prospecting experience more productive for small scale miners.

